
Step 2-1

Step 2-2

Step 3

WARNING! Pinch Point

level check

Warning

Step 4

Step 5

Step 6

Lock up

1.

2.

G

Step 7-1

Step 7-2

Tilt Torque Adjust

5 mm

2°

-12°

Swivel

5 mm




±60°

Rotate

Cable Management

10mm

±2°



UP
MADE IN
TAIWAN